

# **NAVIGATION SAFETY NOTICE**

**Date & time of issue: 21/02/2020**

**Number: 07/20**

**Message: No. 4 Beacon Port Nelson absent**

No. 4 Beacon (Light characteristic Iso R 2s) Position - 41° 15.48.6S 173°15.44.6E marking the extremity of the dredged channel is absent. A temporary yellow buoy with a yellow flashing light has been put in its position until such a time a new beacon can be driven.

Vessels are to navigate with caution when transiting the cut.

The beacon will be replaced as soon as is possible.

**Issued by:** Nelson Harbourmaster

**Valid to:** Until further notice

Contact Duty Pilot for any further information:

Phone: 03 5393879

Email: [duty.pilot@portnelson.co.nz](mailto:duty.pilot@portnelson.co.nz)