

# **NAVIGATION SAFETY NOTICE**

**Date & time of issue:** 10/02/2020

**Number:** 05/2020

**Message:** No. 3 Beacon Port Nelson is missing

No. 3 Beacon (Light characteristic Iso R 2s) Position - 41° 15.82S 173°15.65E marking the extremity of the dredged channel has been knocked over. A temporary orange buoy with an orange flashing light has been put in its position until such a time a new pile can be driven.

Vessels are to navigate with caution when transiting the cut.



The beacon will be replaced as soon as is possible.

**Issued by:** Nelson Harbourmaster

**Valid to:** Until further notice

Contact Duty Pilot for any further information:

Phone: 03 5393879

Email: [duty.pilot@portnelson.co.nz](mailto:duty.pilot@portnelson.co.nz)